



Superior Distribution Ctr.

1142 South First St.

Turlock, CA, 95380

Phone: (209) 667-7051

(800) 457-1728

FAX: (209) 667-8208

NEW PRODUCTS

NEW REPLACEMENT ALTERNATORS, STARTERS, AND COMPONENTS




ABO0027

**IR/IF;
12-VOLT; 70 AMP;**

LESTER 13376;
PIC 220-279, -A;

Used on:
1991-93 Mercedes 190E
1995 Mercedes 300D

REPL.: BOSCH
0-120-485-011, -2,
-22,
0-123-315-005



ADR0281

**FOR 21SI SERIES,
12-VOLT; 125 AMP;**

LESTER 8029;
PIC 240-882A;

3-Wire Hook-up;
Used on Case Equipment;

REPL.: DELCO
1117898;
CASE
1983221C1,
1987560C1



AMN0011

**IR/EF;
12-VOLT; 65 AMP;**

LESTER 12177; PIC 293-14;
1-V Pulley;

Used on OMC, Pleasurecraft, Thermo Electron, Volvo-Penta;

REPL.: MANDO
AC165618, M59819;
VOLVO
3854182-7, 3856600-6, 3857561,
3860171




ABO0226

**IR/IF;
12-VOLT; 160 AMP;**

LESTER 12490;
PIC 220-5300;

Used to Replace Delco and Leece Neville Series Alternators
on HD Truck Applications

REPL.: BOSCH
0-124-525-085



AFD0140


**FOR 6G SERIES;
12-VOLT; 105 AMP;**

11:00 Plug Position;

LESTER 8304;
PIC 250-414;

Used on:
2003-04 Ford Mustang w/4.6L

REPL.: FORD
2R3V-10300-BA,
2R3Z-10346-BA, -BB



AMN0017

**IR/IF;
12-VOLT; 95 AMP;**

LESTER 13783; PIC 203-5033, 208-411;
Used on:

1999-03 Hyundai Sonata w/2.4L
2001-03 Kia Magentis w/2.4L
2001-03 Kia Optima w/2.4L

REPL.: MANDO
AB195126;
HYUNDAI
37300-38310;
VALEO
TA000A29102



Superior Distribution Ctr.

1142 South First St.

Turlock, CA, 95380

Phone: (209) 667-7051

(800) 457-1728

FAX: (209) 667-8208

NEW PRODUCTS

NEW REPLACEMENT ALTERNATORS, STARTERS, AND COMPONENTS

The information herein is based upon data which we believe to be correct and believe to have been obtained from reliable sources, but no representation is made herein, nor should any be implied, regarding the accuracy of any such information and we assume no liability for any errors or omissions in any such information. Any original equipment manufacturers or other manufacturers or distributors, whose names, numbers, pictures, symbols, products and/or descriptions are, or may be, listed or shown herein are used for reference purposes only and there is no representation made or intended, nor should any be implied, that any item reference herein is the product of, or was manufactured and/or distributed, by, the referenced manufacturer or distributor, as the case may be.

This brochure is intended for reference purposes only. For pricing or terms and conditions, please refer to your price sheet.

5/08-1



AMT0014
IR/IF;
12-VOLT; 90 AMP;

LESTER 13575;
PIC 203-420, -A;
Used on:
1995-00 Chrysler Cirrus w/2.5L
1995-00 Dodge Stratus w/2.5L

REPL.: MITSUBISHI
A2TA3791, -7491;
CHRYSLER
4609101, -9125,
4609129, -9320



AMT0078
IR/IF;
12-VOLT; 60 AMP;

LESTER 13227;
PIC 203-355, -A;
Used on:
1990-93 Mazda Miata w/1.6L

REPL.: MITSUBISHI
A5T01577, -03677;
MAZDA
B61P-18-300, -C,
B61P-18-300D, -E



AMT0109
IR/IF;
12-VOLT; 65 AMP;

LESTER 13432;
PIC 203-392, -A;
Used on:
1990-92 Mazda Miata w/1.6L

REPL.: MITSUBISHI
A5T01977,
A5T03777;
MAZDA
B64J-18-300A, -B



AND0050
IR/IF;
12-VOLT; 55 AMP;

LESTER 13214;
PIC 290-240;
Used on:
1989-95 GEO Metro w/1.0L
1989-92 Suzuki Swift w/1.3L

REPL.: DENSO
100211-6720;
GENERAL MOTORS
96030337, 96060337;
SUZUKI
31400-60B40



AMT0073
IR/IF;
12-VOLT; 90 AMP;

LESTER 13598;
PIC 203-468;
Used on:
1996 Dodge Stealth w/3.0L
1997-99 Mitsubishi 3000GT w/3.0L

REPL.: MITSUBISHI
A3T12391;
MITSUBISHI MOTORS
MD324756,
MD354816



AMT0100
IR/IF;
12-VOLT; 125 AMP;

LESTER 13821;
PIC 203-5055;
Used on:
1999-02 Mercury Villager w/3.3L
1999-02 Nissan Quest w/3.3L

REPL.: MITSUBISHI
A3TA5691;
FORD
XF52-10300-AC,
XF5Z-10346-AA;
NISSAN
23100-7B000



AND0010
IR/IF;
12-VOLT; 100 AMP;

LESTER 13384;
PIC 290-325, -A;
Used on:
1990-92 Lexus LS400

REPL.: DENSO
100211-6060,
100211-6350;
TOYOTA
27060-50010, -1



AND0080
IR/IF;
12-VOLT; 80 AMP;

LESTER 13507;
PIC 290-328, -A;
Used on:
1992-96 Honda Prelude w/2.2L
1992-96 Honda Prelude w/2.3L

REPL.: DENSO
100211-8190, -8750,
100211-8770.
101211-5840, -70;
HONDA
31100-P12-A01, -2,
31100-P14-A02,
31100-PT2-003